



Title: METHOD FOR PRODUCING
METAL FIBERS
Serial No. 10/612,232




Figure 1




Figure 2




Figure 3



Figure 4A




Figure 4B




Figure 5A




Figure 5B




Figure 5C




Figure 5D




Figure 5E




Figure 5F



Figure 5G




Figure 5H




Figure 6A




Figure 6B




Figure 6C




Figure 6D




Figure 7A



Figure 7B



Figure 7C




Figure 7D




Figure 7E




Figure 8




Figure 9




Figure 10

Title: METHOD FOR PRODUCING
METAL FIBERS
Serial No. 10/612,232




Figure 11

Title: METHOD FOR PRODUCING
METAL FIBERS
Serial No. 10/612,232




Figure 12A




Figure 12B

Title: METHOD FOR PRODUCING
METAL FIBERS
Serial No. 10/612,232




Figure 12C

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☐ FADED TEXT OR DRAWING
- ☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☒ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☐ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.